

Page No.....

FIRST INFORMATION OF A COGNIZABLE CRIME REPORT UNDER SECTION 154 CRIMINAL PROCEDURE CODE AT POLICE STATION - HENGLEP

Sub-Division: Henglep

District: Churachandpur

Date & Hr. of Occurrence: Not specified

FIR NO. 33(10)2023 HLP-PS U/S 379/34-IPC & Sec. 3 of PDPP Act.

Date & Hour when reported	Place of Occurrence, Distance & Direction from Police Station	Date of despatch from Police Station		
26-10-2023 at 01:00 p.m.	In between Chongchin and Saihum Villages, Henglep Sub-Division, Churachandpur	26-10-2023		

N B: A first information must be authenticated by the signature, mark of thumb impression of informant and attested by the signature of the officer recording it.

Name & residence of informant/ complainant	Name & residence of accused	Brief description of offence with section and of property carried off, if any	Steps taken regarding investigation	Results of the case	
Th. David Khupminlun (34), Manager, Thanlon Sub-Division, MSPDCL. Contact No. 8730992987	Unknown miscreants.	Theft, mischief causing damage to public property with common intention. Punishable U/S 379/34-IPC & Sec. 3 of PDPP Act.	SI Shonthong will please investigate the case.		

O.E - Overleaf

OC/HLP-PS


Officer-In-Charge Henglep Police Station Churachandpur, Manipur Signed Designation

(Inspector Holkhomang Haokip) Officer-in-Charge

Henglep Police Station Officer-In-Charge Henglep Police Station

Churachandpur, Manipur

The Officer-in-Charge Henglep Police Station Churachandpur District, Manipur.



Sir

I, undersigned would like to report that on 10/10/2023 at @ 1:30 Pm received a reliable information that there was a stolen material of 11KV HT line for power supply of Saihum Village from Chongchin Village. Under Henglep Sub Division, Churachandpur District. Manipur,

During Inspection/ Survey self and my teams reach two villages i.e. Chongchin village and Saihum village and found that stolen by unknown persons. List of the stolen materials were noted bellows:-

SI	Description	Unit	Qnty	Rate (Rs)	Amount (Rs)
Vo.	0 T D (MO-CD 24)	Nos	36	18174.00	654264.00
1	9m S.T.P (410:SP-31)	Nos	6	319.80	1918.80
2	Pole top Bracket		6	292.50	1755.00
3	Back Clamp for Pole top Bracket		6	1531.40	9188.00
4	Cross arm(75x40)mm	Nos	6	292.50	1755.40
5	Back Clamp for X-arm	Set	15	3368.30	50524.50
7	2.2m D.P Channel X-arm (75x40)mm 11KV Disc. Insulator (Complete set i/c Tension	Set	90	1469.00	132210.00
201	Clamps Hardware)	Nos	18	767.00	13806.00
8	11KV Insulator with Pin	KM	4	75709.40	302837.60
9	ACSR Conductor(Rabbit)	Set	36	2761.20	99403.20
10	Stay set complete with stay wire base plate, stay rode etc	Jet	HOLE P	di liama	A LILLIANS
44	Stay Clamp	Set	36	292.50	10530.00
11	Bracing for D.P. Structure Set (50x 50 x6)mm D S	Set	15	5913.70	88705.50
	Angle	Mac	60	292.50	17550.00
13	Clamp for DP bracing	Nos	00	202.00	1384448.00
A	Total cost of materials		1-1-1	and forty oic	

Rs. 13, 84,448 (thirteen lakhs eighty four thousand four hundred and forty eight) only/-

It is therefore, requested kindly initiate and takes necessary legal action against the accused persons who were involved in the act, as per law of the land and to recover the same as early as possible. I couldn't able to submit my complain report well in time due to survey of the lost material under Henglep Sub Division, Churachandpur District.

Dated:- The 25th October, 2023

This report is treated as an O.E. of FIR NO. 04 33 (10) 2023 HLB-PS U/S 379/34-186 &

Sec. 3 y PDPP Het.

Henglep Police Station Churachandpur, Manipur Yours Sincerety

(Th. David Khupminlum 34 yrs

Manager Thanlon Sub-Division,

MSPDCL. # 8730992987